



FLOOR MAT MISHAP



The M-ATV is not NMC if it's missing the mats—but why increase your risk of injury? Replace a missing rear floor mat (left-side) with NSN 2540-01-577-0620. Use NSN 2540-01-577-0627 to replace the rear right-side mat.



Wondering what to do with that unsecured equipment? Take a look at WP 0039 in TM 9-2355-335-10 for the lowdown on how to properly secure and stow equipment inside the M-ATV.